The Harman EASY Touch Control Software Update 21.04.20 includes:

- • New home screen LB/Empty button allowing quick access to adjust hopper fill when using the fuel gauge feature.
- • Reduced feed cycles during low burn for faster stove shutdowns.
- • More consistent operation during windy conditions reducing interruptions to the distribution blower airflow.

Highlights from previous updates:

Extended performance history
To provide even better troubleshooting data, we have increased frequency and duration of the history data being saved. The product's performance is now saved every 60 seconds for 3 months, versus 4 days. Also note, if the power goes out, the data will not be lost. The history files can be saved easily onto a USB for service technicians.

Faster ignition
The ignition cycle has been improved with feed concentrated at start, helping all models ignite faster with pellets of varying quality.

Notes:
• Software updates include enhancements from all prior updates, including fixing displaced icons.

• If a customer is experiencing issues with a Harman pellet product with EASY Touch Control, the consumer or service technician should perform the latest software update and test the unit before replacing parts.

• Software Updates are available on the Downloads tab of all Harman EASY Touch product pages. For example, https://www.harmanstoves.com/Products/Allure50-Pellet-Stove.aspx?page=Downloads :