

The Harman EASY Touch Control Software Update 23.02.14 includes:

- Correction for over feeding and pushing unburned pellets into the ashpan during ignition
- Faster shut down and better ignition
- Reduces the need to replace feed motors after several years due to feed cycle drift

Notes:

- Software updates include enhancements from all prior updates, including fixing displaced icons, extended performance history for 3 months, and faster ignition.
- If a customer is experiencing issues with a Harman pellet product with EASY Touch Control, the consumer or service technician should perform the latest software update and test the unit before replacing parts.
- Software Updates are available on the Downloads tab of all Harman EASY Touch product pages. For example, [Absolute63 Pellet Stoves | Harman Stoves](#).

Absolute63 Pellet Stove shown in Matte Black

OVERVIEW FEATURES/OPTIONS SPECIFICATIONS **DOWNLOADS**

Absolute63 Pellet Stove
Starting at \$5,539
Product only. Pricing exclusions apply. Contact a dealer for more information.

Product Brochures

- 📄 Brochure
- 📄 EASY Touch Control Quickstart Guide

Installation Manuals

- 📄 Install Manual

Owner's Manuals

- 📄 Owners Manual
- 📄 Owners Manual - Canadian French
- 📄 Battery Backup Options
- 📄 EASY Touch Control Owners Manual
- 📄 **Software Update: Easy Touch Control - W.**
- 📄 **Software Update: Easy Touch Control - How to Update**
- 📄 **Software Update: EASY Touch control file 23.02.14 zip file.**