

### The Harman EASY Touch Control Software Update 24.04.15 includes:

- Combustion Fan RPM error message which disables the feed and igniter during RPM fault
- Compatibility added for 3-20-777552, 3-20-777562, 3-20-05372, 3-20-05382 controls
- Also includes prior updates such as:
  - Correction for over feeding and pushing unburned pellets into the ashpan during ignition
  - Faster shut down and better ignition
  - Reduces the need to replace feed motors after several years due to feed cycle drift

### Notes:

- Software updates include enhancements from all prior updates, including fixing displaced icons, extended performance history for 3 months, and faster ignition.
- If a customer is experiencing issues with a Harman pellet product with EASY Touch Control, the consumer or service technician should perform the latest software update and test the unit before replacing parts.
- Software Updates are available on the Downloads tab of all Harman EASY Touch product pages. For example, **Absolute63 Pellet Stoves | Harman Stoves.**

OVERVIEW	SPECS	DOWNLOADS	FEATURES/OPTIONS
----------	-------	-----------	------------------

#### Harman Absolute63 Pellet Stove

##### Product Brochures

- Brochure
- EASY Touch Control Quickstart Guide

##### Installation Manuals

- Install Manual

##### Owner's Manuals

- Owners Manual
- Owners Manual - Canadian French
- Battery Backup Options
- EASY Touch Control Owners Manual
- Software Update:** Easy Touch Control - What's New
- Software Update:** Easy Touch Control - How to Update
- Software Update:** EASY Touch control file 24.04.15 (zip format)

