

PC45 AIR PUMP REPLACEMENT KIT

When replacing a Denver Gardner air pump in a pressure ignition system you will need to order the air pump replacement kit (part number 1-00-724209). The replacement Hi-Blow pump (part number 3-20-02679) has a different mounting bracket and some slight wiring changes supplied in the replacement kit. [Attached](#) are detailed step-by-step instructions for installation.

In This Edition:

- PC45 Air Pump Replacement
- Obsolete Venting SKU
- Obsolete Parts

OBSOLETE VENTING SKU

Effective March 31, 2011 the following venting SKU will be obsolete.

Obsolete Part Number	Part Description	Replacement SKU
SRVLINK-ADP	Chimney Liner Term Kit	DV-46DVA-GK

OBSOLETE PARTS

Effective March 1, 2011 the following parts will be obsolete.

Part Number	Part Description
1-00-869466	1/2 x 1/8 Pin HFR GSKt
1-10-00893	RS/PIN Burn Pot -Sales
1-10-00965	Pin control Plate Asy
2-00-06023	RS/PON Door Hinge Top
2-00-06078	RRS/PIN Flue Tube Baff
1-00-00867	CW30 HANDLE ASY/ASH D
1-10-00465	CW30 DAMPER WELDMENT-
1-10-00638	CW30 DAMPER ARM-SALES
1-10-00641	CW30 DAMPER FRAME-SAL
1-10-00734	CW30 FILLER PLATE-SAL
1-10-15027	SF150 ASH PAN-SALES
3-00-00453	CW30 GRATE-CAST
3-31-00303-100	8 CIRC BOARD SUPPORTS-I
4-31-00124	PAW BOLT 3/8 X 2-3/4-

[Back to Top](#)

