



IMPORTANT: THIS IS DATED INFORMATION. Parts must be ordered from a dealer or distributor. **Hearth and Home Technologies does not sell directly to consumers.** Provide model number and serial number when requesting service parts from your dealer or distributor.



**Stocked
at Depot**

| ITEM | DESCRIPTION | COMMENTS | PART NUMBER | |
|------|--|---------------------|-------------|---|
| 1 | Starter Collar | | SRV22069 | Y |
| 2 | Face, Top Front (overlay only) | No longer available | 24132 | |
| 3 | Face, Upper Front (overlay only) | No longer available | 12145E | |
| 4 | Smokeshield | No longer available | 12831B | |
| 5 | Firescreen Assembly - Qty. 2 req. | Pre 25/92 | 12048A | Y |
| | | Post 25/92 | 16765 | Y |
| 6 | Refractory, Side - Qty. 2 req. | Pre 26/91 | 11821A | |
| | | 26/91 thru 25/92 | 16757 | |
| | | Post 25/92 | 17180A | |
| 7 | Grate | | GR40 | Y |
| 8 | Face, Lower Front (overlay only) | | SRV12848BK | |
| 9 | Refractory, Hearth | Pre 25/92 | 12033A | |
| | | Post 25/92 | 17176B | |
| 10 | Refractory, Back | Pre 26/91 | 12031A | |
| | | 26/91 thru 25/92 | 16756A | |
| | | Post 25/92 | 17179B | |
| | Ashlip Ceramic | No longer available | 13623B | |
| | Ashlip Metal | No longer available | 16763A | |
| | Damper Repair Kit | | SRV32828 | Y |
| | Firescreen Hairpin Clip | Pkg of 24 | 101025/24 | Y |
| | Firescreen Rod | Qty. 2 req. | SRV12052 | Y |
| | Smoke Baffle | No longer available | 14079B | |
| | Smokeshield Extended | No longer available | 12831B | |
| | Installation Instructions & Owner's Manual | No longer available | 12955 | |