



Part number list on following page.

Beginning Manufacturing Date: July 2004  
Ending Manufacturing Date: Oct 2004

IMPORTANT: THIS IS DATED INFORMATION. When requesting service or replacement parts for your appliance please provide model number and serial number. All parts listed in this manual may be ordered from an authorized dealer.



Stocked  
at Depot

ITEM	DESCRIPTION	COMMENTS	PART NUMBER	
	Electric Log Assy	No longer available	4030-055	
1	Heater Face Cover	No longer available	4030-100	
2	31 in. Upper Glass Retainer	No longer available	4030-218	
3	Andiron Bracket	No longer available	4030-171	
4	Andiron, Cast, Raw	Qty 2 req	80784	
5	QV32E Refractory Assy			
	31 in. QV Refractory Side LH	No longer available	4030-831	
	32 in. QV Refractory Side RH	No longer available	4030-832	
	32 in. QV Hearth Refractory LH	No longer available	4030-833	
	32 in. QV Hearth Refractory RH	No longer available	4030-834	
6	Flame Tray Support LH	No longer available	4030-165	
7	31 in. Rock Retainer	No longer available	4030-219	
8	Light Tray Assy	No longer available	SRV-020	
8.1	Flame Element Replacement Kit	No longer available	4030-200	
8.2	Halogen Light		33961	Y
8.3	Light Receptacle	No longer available	33962	
8.4	Motor w/Vinyl Cover Assy	No longer available	4030-883	
9	31 in. Upper Face Panel	No longer available	4030-217	
10	31 in. Screen & Rod Assy	No longer available	4030-050	
11	31 in. Screen Panel Assy	No longer available	4030-051	
12	31 in. Screen Rod	No longer available	4030-221	
13	Screen Rod Retainer	No longer available	4030-158	
14	Flame Tray Support RH	No longer available	4030-166	
15	QV Grate Assy	No longer available	4030-898	
16	Ember Bed Glass Panel	No longer available	4030-803	
17	26/31 in. Back Glass Panel	No longer available	4038-810	
18	26/31 in. Lenticular Lens	No longer available	4030-840	
19	Reflective Flame Decal	No longer available	4021-190	
20	Power Cord	No longer available	4030-802	
21	Hood Clip	Pkg of 24	047-805-24	Y
	Ember bed	No longer available	4030-914	
	Firescreen Ring	Pkg of 10	11857B/10	
	Handle Screen		SRV10002	
	Lava Rock		4021-296	
	Painted Teco-Sil Rock	No longer available	4030-811	
	Strain Relief	No longer available	4030-873	
	Strain Relief Bushing	No longer available	10203	
	QV Installation Instructions		4030-240	